




## PLI Support Guide: Bluetooth Connection – R10 & Access

**Summary:** This guide will show you how to make a Bluetooth Connection between a Data Collector w/ Trimble Access and an R10 Rover.

1. Open up Trimble Access and Select "Settings."



2. Click "Connect."



### Pittsburgh Office

85 11<sup>th</sup> Street  
Ambridge, PA 15003  
Ph: (724) 266-1600  
Fax: (724) 266-8161

### Columbus Office

372 Morrison Rd., Suite D  
Columbus, OH 43213  
Ph: (614) 759-1000  
Fax: (614) 759-7059

### Cincinnati Office

820-B Lebanon Street  
Monroe, OH 45050  
Ph: (513) 539-0022  
Fax: (513) 539-0033

### Akron Office


2567 S. Arlington Rd., Suite 5  
Akron, OH 44319  
Ph: (330) 633-4900  
Fax: (330) 633-4999

### WV Office


504 Old Goff Mtn. Rd.  
Cross Lanes, WV 25313  
Ph: (304) 776-1831  
Fax: (304) 776-6790



3. Click "Bluetooth."



4. Click "Config."



**Pittsburgh Office**

85 11<sup>th</sup> Street  
Ambridge, PA 15003  
Ph: (724) 266-1600  
Fax: (724) 266-8161

**Columbus Office**

372 Morrison Rd., Suite D  
Columbus, OH 43213  
Ph: (614) 759-1000  
Fax: (614) 759-7059

**Cincinnati Office**

820-B Lebanon Street  
Monroe, OH 45050  
Ph: (513) 539-0022  
Fax: (513) 539-0033

**Akron Office**

2567 S. Arlington Rd., Suite 5  
Akron, OH 44319  
Ph: (330) 633-4900  
Fax: (330) 633-4999

**WV Office**

504 Old Goff Mtn. Rd.  
Cross Lanes, WV 25313  
Ph: (304) 776-1831  
Fax: (304) 776-6790



5. Click "Add new device..."



6. At this point, your Data Collector will scan for any available Bluetooth connections. (If you are doing this near several other Bluetooth devices, verify the device by the serial # underneath the device.)



**Pittsburgh Office**

85 11<sup>th</sup> Street  
Ambridge, PA 15003  
Ph: (724) 266-1600  
Fax: (724) 266-8161

**Columbus Office**

372 Morrison Rd., Suite D  
Columbus, OH 43213  
Ph: (614) 759-1000  
Fax: (614) 759-7059

**Cincinnati Office**

820-B Lebanon Street  
Monroe, OH 45050  
Ph: (513) 539-0022  
Fax: (513) 539-0033

**Akron Office**


2567 S. Arlington Rd., Suite 5  
Akron, OH 44319  
Ph: (330) 633-4900  
Fax: (330) 633-4999

**WV Office**


504 Old Goff Mtn. Rd.  
Cross Lanes, WV 25313  
Ph: (304) 776-1831  
Fax: (304) 776-6790



7. Click on your device and then click “Next.” Your R10 should not require a passcode.



8. Now your R10 has been connected. Click “Done.”



**Pittsburgh Office**

85 11<sup>th</sup> Street  
Ambridge, PA 15003  
Ph: (724) 266-1600  
Fax: (724) 266-8161

**Columbus Office**

372 Morrison Rd., Suite D  
Columbus, OH 43213  
Ph: (614) 759-1000  
Fax: (614) 759-7059

**Cincinnati Office**

820-B Lebanon Street  
Monroe, OH 45050  
Ph: (513) 539-0022  
Fax: (513) 539-0033

**Akron Office**


2567 S. Arlington Rd., Suite 5  
Akron, OH 44319  
Ph: (330) 633-4900  
Fax: (330) 633-4999

**WV Office**


504 Old Goff Mtn. Rd.  
Cross Lanes, WV 25313  
Ph: (304) 776-1831  
Fax: (304) 776-6790



9. This screen shows that you now have your R10 as a connected device. Click "OK."



10. Finally, select your R10 as either a GNSS Base or GNSS Rover. Once this is complete, Trimble Access will keep that unit as the default Rover or Base. You're now set!



**Pittsburgh Office**

85 11<sup>th</sup> Street  
Ambridge, PA 15003  
Ph: (724) 266-1600  
Fax: (724) 266-8161

**Columbus Office**

372 Morrison Rd., Suite D  
Columbus, OH 43213  
Ph: (614) 759-1000  
Fax: (614) 759-7059

**Cincinnati Office**

820-B Lebanon Street  
Monroe, OH 45050  
Ph: (513) 539-0022  
Fax: (513) 539-0033

**Akron Office**

2567 S. Arlington Rd., Suite 5  
Akron, OH 44319  
Ph: (330) 633-4900  
Fax: (330) 633-4999

**WV Office**

504 Old Goff Mtn. Rd.  
Cross Lanes, WV 25313  
Ph: (304) 776-1831  
Fax: (304) 776-6790