



Survey Rental Equipment

Conventional Total Stations

Nikon NPL-322, DTM-322
Nikon NPL-522, DTM-522
Nikon Nivo 3m, 2m
Nikon C Series
Trimble M1
Trimble M3

Robotic Total Stations

Trimble S3
Trimble S5
Trimble S6
Trimble S7
Trimble S8
Trimble S9
Trimble VX (Scanning Capability)
Spectra Precision Focus 30/35

Survey Accessories

TDL 450 GPS Radio
Trimble Extended Power Kit
Tri-Max Fiberglass Tripod
Prism Pole & Bipod Kit
360 Conventional Prism
MT-1000 Prism
Mini Tilt Prism
25mm Stakeout Prism Kit
Double Right Angle Prism
90° Eye Piece (Used w/ Conventional Total Stations)
Seco Pole Clamps/Data Collector Cradles
Seco Robotic Traverse Kit w/ Prism
Conventional Tri-brach
Mifi 4G-LTE Mobile Internet Hot Spot
Fixed Height Tripods
2m Fixed Height GPS Pole
8', 12', 15' Prism Pole

Data Collectors

Trimble Geo XT
Trimble Tablet Rugged PC
Trimble TSC2 w/ Internal Radio
Trimble TSC3 w/out Internal Radio
Trimble TSC3 w/ Internal Radio
Spectra Precision Nomad 900
Spectra Precision Ranger 3
<u>Available Software:</u> Trimble Access (w/ Roads & Utility Extensions), Survey Pro, Survey Controller, Layout Pro

GPS Locating

Trimble R6 GPS Receiver
Trimble R8 GPS Receiver
Trimble R10 GPS Receiver

Got Questions? Give Me a Call!



Chris Walker

Rental Manager

724.266.1600

crw@laserinst.com

**Please call for rates & availability.*

Pittsburgh Office

85 11th Street
Ambridge, PA 15003
Ph: (724) 266-1600
Fax: (724) 266-8161

Columbus Office

372 Morrison Rd., Suite D
Columbus, OH 43213
Ph: (614) 759-1000
Fax: (614) 759-7059

Cincinnati Office

820-B Lebanon Street
Monroe, OH 45050
Ph: (513) 539-0022
Fax: (513) 539-0033

Akron Office

2567 S. Arlington Rd., Suite 5
Akron, OH 44319
Ph: (330) 633-4900
Fax: (330) 633-4999

Charleston Office

504 Old Goff Mtn. Rd.
Cross Lanes, WV 25313
Ph: (304) 776-1831
Fax: (304) 776-6790

Bridgeport Office

919 West Main Street
Bridgeport, WV 26330
Ph: (304) 933-3036
Fax: (304) 933-3584